











ASSEMBLY INSTRUCTION


A  3.5x50mm 16pcs+1spare	E  3x14mm 6pcs+1spare
B  3.5x40mm 26pcs+1spare	F  3x25mm 4pcs+1spare
C  3.5x35mm 8pcs+1spare	G  2pcs
D  3x18mm 6pcs+1spare	H  1pcs



① X1




② X1




③ X1




④ X1




⑤ X1




⑥ X1




⑦ X1




⑧ X1




⑨ X1




⑩ X1




⑪ X1




⑫ X1




⑬ X1




⑭ X1




⑮ X2




⑯ X1




⑰ X1




⑱ X1



⑲ X1




⑳ X1




㉑ X2

ASSEMBLY INSTRUCTION




Bx12
Dx2
Ex2

STEP1




Ax6

STEP2




Ax6
Bx6

STEP3




Ax4
Bx6
Ex4
Gx2

STEP4




STEP5



Cx8
Dx4

STEP6



Bx2
Fx4

STEP7